



(844)278-03-48, (473)204-51-73, (343)384-55-89, (843)206-01-48,
(861)203-40-90, (391)204-63-61, (495)268-04-70, (846)206-03-16,
(831)429-08-12, (383)227-86-73, - - (863)308-18-15,
- (812)309-46-40, (845)249-38-78, (347)229-48-12
rtx@nt-rt.ru
- **rextch**.nt-rt.ru

13-1002

UNI-T UT20B

	200	/2000	/20	/200	/300	(1.5%+2)
				200	/300	(2.5%+15)
				2000	/20	(2.5%+10)
				200	/2000	(2.5%+5)
3-	1.5	/9				= 10
						95x 52 x 26
						9
						125



13-1003

UNI-T UT30B

	200	/2000	/20	/200	/500	(0.5%+2)
				200	/500	(1.2%+10)
				200	/2000	(1%+2)
3-				200	/2000	(0.8%+2)
						1.5 /9 /12
						= 10
						130 * 73.5 * 35
						9
						156



13-1004

UNI-T UT30F

	200	/2000	/20	/200	/500	(0.5%+2)
				200	/2	(1%+3)
				20	/200	(1%+2)
				200	/10	(1.8%+2)
				200	/2000	(0.8%+2)
				2	-20	(0.1%+3)
3-						= 10
						130 73.5 35
						9
						156



13-1005

UT33A

3-	400	/4	/40	/400	/500	(0.8% + 1)
	4	/40	/400	/500		(1.2% + 3)
	400	µA/4000	µA/40	/400	/4	/10 (1% + 2)
	400	µA/4000	/40	/400	/4	/10 (1.5% + 5)
	400	/4	/40	/400	/4	/40 (1% + 2)
						5/9/12
						= 10
	490	*	356	*	315	
						1.5 * 2



13-1006

UT33B

3- hold +	200	/2000	/20	/200	/500	(0.5% + 2)
	200	/500				(1.2% + 10)
	200	/200	/10			(1% + 2)
	200	/2000	/20	/200	/20	(0.8% + 2)
			1.5/9/12			Data
						= 10
	130	*	73.5	*	35	
						9



13-1007

UT33C

3-	200	/2000	/20	/200	/500	(0.5% + 2)
	200	/500				(1.2% + 10)
	2000	/20	/200	/10		(1% + 2)
	200	/2000	/20	/200	/20	(0.8% + 2)
	-40 ... 1000	°C/-40 ... 1832	°F			(1% + 3)
						Data hold +
						= 10
	130	*	73.5	*	35	
						9



13-1011

UNI-T UT50C

.....	200	/2	/20	/200	/1000	(0.5% + 1)	
.....	2	/20	/200	/750		(0.8% + 3)	
.....	20	/200	/20			(0.8% + 1)	
.....	20	/200	/20			(1% + 3)	
.....	200	/20	0	/200	/2	/200	(0.8% + 1)
.....	20	/200	/2	/100		(4% + 3)	
(F):.....	-40...	+ 1000 °	/-40...	+ 1832 °			
.....	2	-20				(1.5% + 5)	
3- hold +	Bata	
.....	= 10	
.....	165 x 80 x 38	
.....	270	
.....	9	



13-1013

UNI-T UT60A

.....	400	-	1000	(0.8% + 1)
.....	4	-	750	(1% + 5)
.....	400	-	10	(1% + 2)
.....	400	-	10	(1.5% + 5)
.....	400	-	40	(1% + 2)
.....	40	-	100	(3% + 5)
.....	10	-	10	(0.1% + 3)
6	0.1% - 99.9%
.....	Data hold +
.....	= 10
.....	177 85 40
.....	9
.....	340



13-1014

UNI-T UT60G

.....	600	-	1000	(0.5% + 3)
.....	600	-	1000	(1% + 2)
.....	60	-	10	(1.2% + 3)
.....	60	-	10	(2% + 5)
.....	600	-	60	(1% + 2)
.....	6	-	6	(4% + 3)
.....	6	-	60	(0.05% + 3)
6	-40 ... - + 1000 ... (1% + 3)
.....	Data hold +
.....	= 10
.....	177 85 40
.....	9
.....	320



